Excelbis Labs
1920 E Warner Avenue
Santa Ana, CA 92705

(714) 340-7099
http://excelbislabs.com
Lic# C8-0000059-LIC

Venom OG

Sample ID: 2403EXL0657.2961
Strain: Venom OG
Matrix: Plant
Type: Flower - Cured
Sample Size: ; Batch:

Produced:
Collected: 03/13/2024
Received: 03/13/2024
Completed: 03/19/2024
Batch#: 20240108-SH-BVO

Summary

Test	Date Tested	Result
Batch		Complete
Cannabinoids	03/19/2024	Complete
Moisture	03/19/2024	13.0% - Complete

Cannabinoids

Complete

28.956%	ND	29.760%
Total THC	Total CBD	Total Cannabinoids

Analyte	LOD	LOQ	Result	Result
	mg/g	mg/g	%	mg/g
CBD	0.125	0.250	ND	ND
CBDa	0.125	0.250	ND	ND
CBDV	0.125	1.000	ND	ND
CBG	0.125	0.500	0.8043	8.043
CBGa	0.125	0.250	ND	ND
CBN	0.125	0.250	ND	ND
Δ8-THC	0.125	0.500	ND	ND
Δ9-THC	0.125	0.500	0.2072	2.072
THCa	0.250	0.500	32.7807	327.807
THCV	0.250	0.500	ND	ND
Total THC			**28.956**	**289.560**
Total CBD			**ND**	**ND**
Total CBG			**0.804**	**8.043**
Total			**29.760**	**297.602**

Date Tested: 03/19/2024

Total THC = THCa * 0.877 + Δ9-THC; Total CBD = CBDa * 0.877 + CBD; Total CBG = CBGa * 0.877 + CBG.
Total Cannabinoids = Total THC + Total CBD + Total CBG + minor cannabinoids.
Cannabinoids: HPLC, CAN-SOP-001
Water Activity: Water Activity Meter, WA-SOP-001
Moisture Content: Moisture Analyzer, MO-SOP-001
Foreign Matter: Visual Inspection, FM-SOP-001

Jerry White, PhD
Chief Scientific Officer
03/19/2024

Bryan Zahakaylo
Analyst
03/19/2024